



**EUROP-ARM**

Depuis 1973

## Num'Axes cover + Canifugue collar seal

<https://europarm.fr/en/produit-21295-Num-Axes-cover-Canifugue-collar-seal>



**NUM'AXES**

| SKU      | Designation   | French Law  | MSRP              |
|----------|---|-------------|-------------------|
| NUMP0041 | Couvercle avec joint d'étanchéité collier Canifugue FUG1030 | Vente libre | 12.00 € incl. tax |

### Ensures the watertightness of the Canifugue FUG1030 / FUG1031 collar.

The **Num'Axes lid with seal** effectively protects the battery compartment of the **Canifugue FUG1030** and **Canifugue Mix FUG1031** collars.

- **Compatibility:** Canifugue FUG1030, Canifugue Mix FUG1031
- **Function:** Battery compartment closure and sealing
- **Sealing gasket:** included
- **Material:** Plastic and soft rubber
- **Installation:** direct mounting onto the receiver collar

### Replace the cover on your Num'Axes anti-escape collar

Designed specifically for **Canifugue FUG1030** and **Canifugue Mix FUG1031** receiver collars, this **cover with seal** ensures optimal protection against moisture, dust and splashes.

### An integrated seal for enhanced watertightness

The **flexible gasket** supplied with the cover **seals the battery compartment** and prevents leaks, even when exposed to rain or damp ground. This replacement is recommended if the original cover is worn or lost.

### Quick and durable installation

The collar mounts easily onto the original housing without any special tools. The cover is made of **robust plastic**, and the seal is made of **flexible rubber**, ensuring a reliable and durable closure for intensive use in the field.

### FAQ

#### Is this lid compatible with the Canifugue FUG1032 and FUG1033 models?

No, this model is **specifically designed for the FUG1030 and FUG1031 models**. Other versions require a dedicated cover.

### **Is the gasket included with the lid?**

Yes, the **sealing gasket is integrated** into the product and does not require separate purchase.

### **Why replace this lid?**

A worn or poorly sealed cover can cause **the collar to malfunction** in the event of water infiltration. Replacing it ensures the system's reliability.

*Les prix de vente conseillés sont mentionnés à titre indicatif. Les armuriers sont libres de vendre au prix qu'ils souhaitent. Textes et photos non contractuels, sujet à modification.*